

List of work done from April 1, 2026 to April 30, 2026

DG Battery Purchase

1. New battery purchased for C, F and G Block DG.

A3 Block lift renovation related work –

1. New belt and roller installed in A3 Block lift.
2. Renovation of A3 block lift which was not operational for years and many parts of the lift found missing has been completed.
3. A3 Block lift becomes fully operational.

Lift related work-

1. F Block lift door repaired and installed.
2. F Block lift gate work done.
3. G Block lift gate jam issue resolved
4. G Block lift sensor issue resolved.
5. G Block lift mother board issue resolved.
6. G Block lift level issue resolved.
7. G Block lift new rid installed.
8. A Block lift button changed.
9. Servicing of all blocks lifts done.
10. G block lift not working issue resolved.
11. E block lift levelling issue resolved.
12. E Block lift not working issue resolved.
13. E Block lift fan issue resolved.
14. New fan installed in C Block lift.
15. D Block lift not working issue resolved.
16. C Block lift not working issue resolved.
17. B1 block lift sticking issue resolved.
18. B1 Block lift belt changed.

Water Tank cleaning related work

1. Tank cleaning of A Block done.
2. Tank cleaning of B1 Block done.
3. Tank cleaning of B2 Block done.

4. Tank cleaning of C Block done.
5. Tank cleaning of D Block done.
6. Tank cleaning of E Block done.
7. Tank cleaning of F Block done.
8. Tank cleaning of G Block done.
9. Tank cleaning of all blocks done.

Society Building Internal/ Corridor Repairing and Common area Maintenance work –

1. Nali repairing and plaster work done at different blocks.
2. Parking area cement plaster and repairing work done in different blocks.
3. Common area cement plaster and repairing work done for internal roads.
4. Cement and plaster work done in A Block.
5. Cement and plaster work done at E block staircase area.
6. Cement and plaster work done in D Block parking area.
7. Broken nali repairing and plaster work done in D Block Nali.
8. Broken nali repairing work done in E Block nali.
9. Cement plaster and repairing work getting done at different parking areas.
10. Cement plaster and repairing work done for gate side road.
11. Cement plaster and repairing work done for internal roads of society.
12. Main gate road ghutai work done.
13. Society inside road rori levelling and plaster work done.
14. Cement plaster work done for nali covering at G Block.
15. Cement plaster work done for motor wire covering at G Block.
16. Road side nali cement plaster and repairing work done.

Iron Jali related work-

1. New Iron Jali installation work in G Block getting done.

Sewer related work

1. Sewer jam near security gate, common area road towards gate opened and water service resumed.
2. Main road gallery sewer cleaning done.
3. Common area sewer cleaning of G block done.
4. G Block sewer jam issue resolved.
5. F Block sewer jam issue resolved.

Borewell and Motor related work-

1. D & E Block motor capacitor changed.
2. Motor wire burnt of F Block fixed.
3. Starter panel wire burnt issue of F Block resolved.
4. Starter panel wire burnt issue resolved of G block.
5. Motor wire burnt of E block resolved.
6. Multiple wire burnt issues related to motor and starter panel fixed time to time.

Water leakage and plumbing related work

1. F Block parking pipe broken issue resolved.
2. F Block tank leakage issue resolved.
3. Motor related plumbing issues of different blocks resolved.
4. Regular fulfillment of water supply in different blocks.
5. G Block pipe blockage issue resolved.
6. C Block pipe blockage issue resolved.
7. A Block pipe leakage issue resolved.
8. B1 Block pipe broken issue resolved.
9. Pipe blockage issues at different blocks resolved.

Welding work

1. Welding work done in D block staircase railing.
2. Welding work done in G block staircase railing.

Electrical related work

1. C Block lift new 4 pole MCB installed.
2. F Block common area light issue fixed.
3. G Block one side common area lights not working issue fixed.
4. C Block changeover issue resolved.
5. E Block wiring fixing done.
6. G Block common area electrical issue fixed.
7. Boom barrier electrical issue fixed.
8. Electrical issues related to different blocks of common area resolved as and where required.

Blower for electrical panel & Bulb, Holders & Halogen installation work

1. Blower work done for all meter panels on regular basis.

2. Multiple times blower work getting done for all blocks meter.
3. Bulbs and holders getting installed in different blocks and common area.
4. Halogens installed as and where required.

Vacuum cleaner cleaning machine related work -

1. Gear hub, gear set, T hub, kharad and auto scrubber changed for cleaner machine.

CCTV related work

1. New wiring fitting getting done for wires broken, damaged and lost connectivity.
2. New POE switch installed and old replaced.
3. Multiple connectors installed.
4. New HDMI cable installed.
5. New CCTV installed in G Block lift.
6. New CCTV installed in G Block parking area.
7. CCTV support box installed.
8. CCTV maintenance work going on.
9. New CCTV installed at gate.
10. Three new CCTV installed and old one replaced due to not working and damage.
11. Ply Board box installation done for CCTV DVR.

Fogging and fogging machine related work

1. Fogging getting done on regular basis.
2. Fogging machine repairing work done.

Housekeeping Related work

1. Gamla removal from different blocks of society.
2. Machine cleaning of all blocks three to four times in the month.
3. Staircase scrubbing and cleaning using machine three to four times in the month.
4. Trees and plants cutting behind C Block.
5. Trees and plants cutting at the society gate.
6. Plants cutting in corridor side of the inside road.
7. Soil and dust removal from society gate and surrounded area.

8. Washing and cleaning of society gate, corner area and all surrounding area of gate on regular basis.
9. Lift cleaning of all blocks on regular basis.
10. Common area cleaning on daily basis.
11. Parking area cleaning on regular basis.
12. Cleaning of two common washrooms and maintenance both offices on regular basis using machine.
13. Washing and cleaning of both fountains on regular basis.
14. Outer area gate side and gallery side cleaning on regular basis.
15. Garbage disposal from garbage vehicle on daily basis.
16. Dustbin washing and cleaning on regular basis.
17. Railing Cleaning of all blocks on regular basis.
18. Side area cleaning beside staircases cleaning on regular basis.
19. Cobweb cleaning of parking area of all blocks.
20. Cobweb cleaning of all tower all floors on regular basis.
21. Gate side area cleaning on regular basis.
22. Guard room cleaning on daily basis.
23. Sweeping and mopping of all blocks' floors on daily basis.
24. Garbage collection from all blocks on daily basis.
25. Regular cleaning and maintenance of surrounded area of fountains and staircase of park.
26. Washing and cleaning of temple on regular basis.
27. Cleaning of partition board, society gate, society boundary wall at society main gate.
28. Kawada removal from society.
29. All blocks Kawad removal from common area and corridor area on regular basis as and when required.
30. Terrace cleaning of all blocks done.

31. Staircase railing cleaning done for all blocks more than 4 to 5 times in a month.
32. Temple cleaning inside outside done.
33. Tree and plants cutting on terrace.
34. Transformer side cleaning done.

Nali Cleaning

1. Nali cleaning of D & E Block done and Malwa thrown outside society.
2. Nali cleaning of G Block done and Malwa thrown outside society.
3. Nali cleaning of F Block done and Malwa thrown outside society.
4. Nali cleaning of common area towards society gate done and Malwa thrown outside society.

Festival Celebration

1. Hanuman Jayanti Poojan Celebration done.

Accountancy & Transparency related work

1. Sharing & Publishing Income & Expenditure Monthly report, NBH sales report, Sales report, Bank statement, Electricity bill on regular basis.
2. Doing maximum transaction through cheque and doing minimum cash recharges as and when required in case of emergencies.
3. Keeping record of all cash recharges and online recharges through QR scanner code and putting it in Income report on monthly basis.
4. Publishing all accounting related information on timely basis with as much as transparency as possible.
5. Sharing and publishing "List of work done in a particular period" on regular basis.
6. Sharing and publishing "Assets added to welfare of Society and Liabilities reduced of Society" on regular basis.
7. Approximately Rs. 44,00,000 work has been done with respect to "Assets / work added to welfare of Society and Liabilities reduced of Society". Society has been handed over to our team from previous RWA at a negative fund/ liability of Rs. 18,00, 000 approximately.
8. All dues of electricity department have been paid off.