List of work done from August 1, 2026 to August 30, 2026

Putty, Level Plast, POP and Primer work

1. Putty, Level Plast and POP work getting done in terrace area of G Block.
2. Putty, Level Plast and POP work getting done in outer gate side area.
3. Putty, Level Plast and POP work getting done in parking area of A Block.
4. Putty, Level Plast and POP work getting done in parking area of B1 Block.
5. Putty, Level Plast and POP work getting done in parking area of B2 Block.
6. Putty, Level Plast and POP work getting done in parking area of C Block.
7. Putty, Level Plast and POP work getting done in parking area of D Block.
8. Putty, Level Plast and POP work getting done in parking area of E Block.
9. Putty, Level Plast and POP work getting done in parking area of F Block.
10. Putty, Level Plast and POP work getting done in parking area of G Block.
11. Putty, Level Plast and POP work getting done in common area of society.
12. Putty, Level Plast and POP work getting done in outer facade area of A Block.
13. Putty, Level Plast and POP work getting done in outer facade area of B1 Block.
14. Putty, Level Plast and POP work getting done in outer facade area of B2 Block.
15. Putty, Level Plast and POP work getting done in outer facade area of C Block.
16. Putty, Level Plast and POP work getting done in outer facade area of D Block.
17. Putty, Level Plast and POP work getting done in outer facade area of E Block.
18. Putty, Level Plast and POP work getting done in outer facade area of F Block.
19. Putty, Level Plast and POP work getting done in outer facade area of G Block.
20. Primer painting done for chamber cover, fountain cover and sewer cover.
21. Putty Level Plast and POP work done on G block terrace boundary wall.
22. Putty, Level Plast and POP work done on F block terrace boundary wall.
23. Maintenance office Putty, POP and level plast work done.
24. Asian Apex Ultima Paint getting done In C Block parking area.
25. Asian Apex Ultima Paint getting done In D Block parking area.
26. Asian Apex Ultima Paint getting done In E Block parking area.

Lift related work

1. New 4 hanging ropes purchased and installed in A3 Block lift.
2. B1 Block lift door belt change.
3. Servicing of all blocks lift done.
4. A1 block lift sound issue resolved.
5. A3 block lift gate issue resolved.
6. E block lift sound issue resolved.
7. F block lift sound issue resolved.
8. G block lift sound issue resolved.
9. D Block lift first floor to ground floor issue resolved.
10. B1 block lift door belt sound issue resolved.
11. B1 block lift senser installed and working.
12. A Block lift door alignment done.
13. D Block lift not working issue resolved.
14. A Block lift cuppler change.

15. A Block lift fourth floor issue resolved.
16. D Block lift issue resolved.
17. A Block lift door motor issue resolved.
18. A3 block lift 5th floor issue resolved.
19. A3 block lift wiring issue resolved.

Boom barrier related work

1. New push button box installed.
2. Remote of boom barrier repaired.
3. Boom barrier hinge issue resolved.

Festival Celebration

1. Rudrabhishek Poojan done in temple.
2. Kheer Prasadam devoted to Lord Shiva and distributed among residents.
3. Grand celebration and flag hoisting of Independence Day done.
4. Sweets and snacks distributed among all residents.
5. Cultural program performed by kids and gifts distributed to children.
6. Balloon decoration done throughout the society and selfie point made for enhancing enjoyment.
7. Grand celebration of Janmashtami Mahotsav.
8. Chhappan Bhog and Bhajan Mandli performance on the eve of Janmashtami.
9.

Borewell and Motor related work-

1. A Block motor extracted and new motor installed.
2. A Block motor extracted, new motor purchased and installed.
3. New motor jointer installed for A Block motor in borewell.
4. G Block motor extracted, new motor purchased and installed.
5. A Block motor starter panel wire short circuit issue resolved.
6. G Block motor wire change.
7. F Block motor extracted, new motor installed.
8. C Block motor capacitor change.
9. Starter panel purchased for B2 block.
10. A Block starter panel issue resolved.
11. G Block starter panel issue resolved.
12. C Block motor wire burnt issue resolved.
13. F Block complete motor wire burnt changed, new wire installed.
14. F block motor starter panel repairing done.
15. F Block motor two time extracted, new motor purchased and installed.
16. F Block motor conduitor purchased and installed.
17. F Block motor conductor change.

Transformer related work

1. Transformer Jumpher burnt resolved by lineman.
2. Transformer related issue resolved by lineman.

New overhead tank installation

1. New overhead tank installed on F Block terrace.

Cleaning machine related work

1. New 60 meter wire purchased for cleaning machine.

Water leakage and plumbing related work

1. D Block terrace pipe blockage issue resolved.
2. F block pipe damage issue resolved.
3. B2 block motor pipe damage issue resolved.
4. B2 Block shaft pipe damage issue resolved.
5. A Block terrace pipe broken change damage issue resolved.
6. New ball cock installed in C Block water tank.
7. New Ball cock installed in B2 Block tank.
8. F Block new tank installed.
9. New pipes and other plumbing work done for F Block tank installation.
10. G Block terrace pipe broken resolved.
11. G Block motor pipe broken resolved.
12. A Block motor pipe broken resolved.
13. A Block parking area damage pipe changed issue resolved.
14. B2 block multiple pipes broken in shaft repaired and new piping done.
15. F Block common area pipe leakage and damage issue resolved.
16. A Block broken pipe damage issue resolved.
17. B2 block pipe broken new pipe installed.
18. F Block broken pipe issue resolved.
19. G Block broken and damaged pipe issue resolved.
20. Motor related plumbing issues of different blocks resolved.
21. Regular fulfillment of water supply in different blocks.

Sewer related work

1. Three sewers of F Block jam opened and issue resolved.
2. Gallery area sewer jam opened towards main gate.
3. D Block sewer jam issue resolved.
4. Sewer cleaning done for B2 Block.
5. Sewer cleaning done for F and G block common passage on regular basis.
6. Main gate sewer jam opened and water supply resumed.
7. Corridor sewer at Gate water and Malwa extraction done multiple times.

Electrical related work

1. G Block main MCB shortage issue resolved.
2. F Block sixth common area light short circuit wire burnt, complete new wiring done.
3. F Block sixth common area light short circuit wire burnt, complete new wiring done.
4. New tubelight installed and wiring done in B2 block sixth floor.
5. A Block motor wire damage at two places resolved.

6. F Block sixth floor complete wiring change.
7. F Block fifth floor complete wiring change.
8. B2 Block MCB Burnt, new MCB installed.
9. F Block MCB change, new mcb installed.
10. New lights installed in temple.
11. G Block wiring short circuit issue resolved.
12. G Block main meter panel short circuit issue resolved.
13. G Block main meter panel new wiring done for different meters wires burnt.
14. F Block common area short circuit in panel wire burnt changed.
15. Fountain wire broken and damaged changed and issue resolved.
16. Fountain wire short circuit issue resolved.
17. Wiring issues related to common area resolved.
18. Wire burnt issue related to motors at different blocks resolved.
19. Starter panel related issues for different motors resolved.
20. Electrical issues related to lifts resolved.
21. Meter room and other electrical related work done as and where required.

Blower for electrical panel & Bulb, tube lights, Holders & Halogen installation work

1. New tube lights installed in b2 block.
2. New switches and sockets installed in B2 block.
3. Blower work done for all meter panels on regular basis.
4. Multiple times blower work getting done for all blocks meter.
5. Bulbs and holders getting installed in different blocks and common area.

Housekeeping Related work

1. Machine cleaning of all blocks three to four times in the month.
2. Staircase scrubbing and cleaning using machine three to four times in the month.
3. Trees and plants cutting behind C Block.
4. Trees and plants cutting at the society gate.
5. Plants cutting in corridor side of the inside road.
6. Soil and dust removal from society gate and surrounded area.
7. Washing and cleaning of society gate, corner area and all surrounding area of gate on regular basis.
8. Lift cleaning of all blocks on regular basis.
9. Common area cleaning on daily basis.
10. Parking area cleaning on regular basis.
11. Cleaning of two common washrooms and maintenance both offices on regular basis using machine.
12. Washing and cleaning of both fountains on regular basis.

13. Outer area gate side and gallery side cleaning on regular basis.
14. Garbage disposal from garbage vehicle on daily basis.
15. Dustbin washing and cleaning on regular basis.
16. Railing Cleaning of all blocks on regular basis.
17. Side area cleaning beside staircases cleaning on regular basis.
18. Cobweb cleaning of parking area of all blocks.
19. Cobweb cleaning of all tower all floors on regular basis.
20. Gate side area cleaning on regular basis.
21. Guard room cleaning on daily basis.
22. Sweeping and mopping of all blocks' floors on daily basis.
23. Garbage collection from all blocks on daily basis.
24. Regular cleaning and maintenance of surrounded area of fountains and staircase of park.
25. Washing and cleaning of temple on regular basis.
26. Cleaning of partition board, society gate, society boundary wall at society main gate.
27. Kawada removal from society.
28. All blocks Kawad removal from common area and corridor area on regular basis as and when required.
29. Terrace cleaning of all blocks done.
30. Staircase railing cleaning done for all blocks more than 4 to 5 times in a month.
31. Temple cleaning inside outside done.
32. Tree and plants cutting on terrace.
33. Gamla removal from different blocks of society.

Nali Cleaning

1. Nali cleaning of D & E Block done and Malwa thrown outside society.
2. Nali cleaning of G Block done and Malwa thrown outside society.
3. Nali cleaning of F Block done and Malwa thrown outside society.
4. Nali cleaning of common area towards society gate done and Malwa thrown outside society.

Accountancy & Transparency related work

1. Sharing & Publishing Income & Expenditure Monthly report, NBH sales report, Sales report, Bank statement, Electricity bill on regular basis.

2. Doing maximum transaction through cheque and doing minimum cash recharges as and when required in case of emergencies.
3. Keeping record of all cash recharges and online recharges through QR scanner code and putting it in Income report on monthly basis.
4. Publishing all accounting related information on timely basis with as much as transparency as possible.
5. Sharing and publishing “List of work done in a particular period” on regular basis.
6. Sharing and publishing “Assets/work added to welfare of Society and Liabilities reduced of Society” on regular basis.
7. Approximately Rs. 51,50,000 works have been done with respect to “Assets / work added to welfare of Society and Liabilities reduced of Society”. Society has been handed over to our team from previous RWA at a negative fund/liability of Rs. 18,00, 000 approximately.
8. All dues of electricity department have been paid off.