

List of work done from July 1, 2026 to July 31, 2026

Putty, Level Plast, POP and Primer work

1. Putty, level Plast and POP work getting done in internal corridors of C Block.
2. Putty, level Plast and POP work getting done in internal corridors of D Block.
3. Putty, level Plast and POP work getting done in internal corridors of B2 Block.
4. Putty, level Plast and POP work getting done in internal corridors of G Block.
5. Putty, level Plast and POP work getting done in internal corridors of E Block.
6. Putty, level Plast and POP work getting done in internal corridors of B1 Block.
7. Putty, level Plast and POP work getting done in internal corridors of F Block.
8. Putty, level Plast and POP work getting done in internal corridors of A Block.
9. Putty, Level Plast and POP work getting done in parking area of A Block.
10. Putty, Level Plast and POP work getting done in parking area of B1 Block.
11. Putty, Level Plast and POP work getting done in parking area of B2 Block.
12. Putty, Level Plast and POP work getting done in parking area of C Block.
13. Putty, Level Plast and POP work getting done in parking area of D Block.
14. Putty, Level Plast and POP work getting done in parking area of E Block.
15. Putty, Level Plast and POP work getting done in parking area of F Block.
16. Putty, Level Plast and POP work getting done in parking area of G Block.
17. Putty, Level Plast and POP work getting done in common area of society.
18. Putty, Level Plast and POP work getting done in outer facade area of A Block.
19. Putty, Level Plast and POP work getting done in outer facade area of B1 Block.
20. Putty, Level Plast and POP work getting done in outer facade area of B2 Block.
21. Putty, Level Plast and POP work getting done in outer facade area of C Block.
22. Putty, Level Plast and POP work getting done in outer facade area of D Block.
23. Putty, Level Plast and POP work getting done in outer facade area of E Block.
24. Putty, Level Plast and POP work getting done in outer facade area of F Block.
25. Putty, Level Plast and POP work getting done in outer facade area of G Block.
26. Primer painting done for chamber cover, fountain cover and sewer cover.

Fire Extinguisher related work

1. Two New fire extinguishers installed on each floor including Ground floor of D Block.
2. Two New fire extinguishers installed on each floor including Ground floor of C Block.
3. Two New fire extinguishers installed on each floor including Ground floor of E Block.
4. Total of 35 new fire extinguishers installed.

Iron and fabricator related work

1. New iron chamber cover installed for A1 Block borewell.
2. New iron chamber installed for F2 Block sewer.
3. New iron chamber cover installed for F Block borewell.
4. New twofold chamber cover made and installed for sewer cover of gallery towards main gate.
5. New chamber cover installed for F and A block sewer.
6. New iron cover sheet made for both fountains.

7. C Block iron jali complete damaged, new iron jali work done and new iron pipe and jali installed.
8. D Block iron jali damaged new jali and iron belt installed.

Mason related work

1. A Block motor new chamber made with bricks and cement.
2. New chamber cement plaster work done for A Block borewell.
3. New chamber for F Block borewell made with bricks and concrete.
4. New chamber cement plaster work done for F Block borewell.
5. Cement plaster and concrete work done for stabilizing sewer area of main gate.
6. Cement and plaster work done to install chamber cover for main gate sewer.
7. Cement and plaster work done for installation of other sewer covers in F and A Block.
8. F2 Block sewer cover cement plaster levelling work and installation of new iron chamber cover.

Lift related work

1. A Block lift shoe changed.
2. A3 block lift rope damage issue resolved.
3. G Block hooter battery changed.
4. F Block hooter battery changed.
5. E Block lift door drive changed.
6. E Block lift motor changed.
7. B1 lift not working issue resolved.
8. E Block lift issue resolved.
9. A3 Block lift ground floor door issue resolved.
10. F Block lift door drive changed.
11. A3 Block lift new coupler installed.
12. B1 Block lift lights changed.
13. A Block lift hooter battery changed.
14. A block lift main door card changed.
15. Servicing of all blocks lift done.
16. B1 lift alarm working.
17. A3 lift alarm working.
18. B1 lift wire damage issue resolved.
19. E Block lift alarm working.
20. G Block lift not working issue resolved.
21. F Block lift door not opening issue resolved.
22. B1 Block lift door issue resolved.
23. D Block lift not working issue resolved.
24. E Block lift gate issue resolved.
25. A Block lift coupler damage issue resolved.
26. A Block lift door not opening issue resolved.
27. A Block lift landing issue resolved.

Borewell and Motor related work-

1. A Block motor wire short circuit issue resolved.
2. E Block starter panel capacitor changed.
3. Two new pipes installed in F Block borewell.
4. F Block motor extracted, new motor installed.
5. New wires for borewell installed for F Block motor.
6. A Block motor extracted new motor installed.
7. A Block motor wire burnt changed.
8. A Block starter panel capacitor changed.
9. New MCB installed for motor in A Block.
10. F Block motor extracted new motor installed.
11. New MCB installed for F Block motor.
12. A Block motor wire short new wiring done.
13. G Block motor extracted and new motor installed.
14. A Block motor main pipe damage resolved.
15. A Block borewell internal wire short circuit and motor wire burnt issue resolved.
16. New capacitor installed for C Block starter panel.
17. C Block motor capacitor wire burnt changed.
18. F Block motor capacitor changed.
19. A Block motor starter panel not working damaged issue resolved.

Transformer related work

1. Transformer Jumper burnt resolved by lineman.
2. Transformer related issue resolved by lineman.

Cleaning machine related work

1. Cleaning machine repairing work done and damaged components changed.

Water leakage and plumbing related work

1. G Block parking area pipe damaged and leakage issue resolved.
2. A Block motor pipe broken resolved.
3. A Block terrace pipe blockage issue resolved.
4. A Block motor pipe damage resolved.
5. A Block parking area damage pipe changed issue resolved.
6. B2 block multiple pipes broken in shaft repaired and new piping done.
7. F Block common area pipe leakage and damage issue resolved.
8. A Block broken pipe damage issue resolved.
9. B2 block pipe broken new pipe installed.
10. New gate valve installed for outflow of fountain water.
11. F Block broken pipe issue resolved.
12. G Block broken and damaged pipe issue resolved.
13. G Block near main panel area pipe damaged and broken issue resolved.
14. C Block broken pipe damage issue resolved.
15. F Block parking area broken pipe damage issue resolved.

16. C Block second pipe leakage and broken issue resolved.
17. E block broken pipe issue resolved.
18. Motor related plumbing issues of different blocks resolved.
19. Regular fulfillment of water supply in different blocks.

Sewer related work

1. Three sewers of F Block jam opened and issue resolved.
2. Gallery area sewer jam opened towards main gate.
3. C Block sewer jam issue resolved.
4. Sewer cleaning done for B2 Block.
5. Sewer cleaning done for F and G block common passage on regular basis.
6. Main gate sewer jam opened and water supply resumed.
7. Corridor sewer at Gate water and Malwa extraction done multiple times.

Electrical related work

1. New MCB installed in A Block for motor.
2. A3 lift auto changeover damage repaired.
3. New MCB installed for F Block borewell.
4. G Block main meter panel short circuit issue resolved.
5. G Block main meter panel new wiring done for different meters wires burnt.
6. F Block common area short circuit in panel wire burnt changed.
7. Fountain wire broken and damaged changed and issue resolved.
8. Fountain wire short circuit issue resolved.
9. Wiring issues related to common area resolved.
10. Wire burnt issue related to motors at different blocks resolved.
11. Starter panel related issues for different motors resolved.
12. Electrical issues related to lifts resolved.
13. Meter room and other electrical related work done as and where required.

Blower for electrical panel & Bulb, tube lights, Holders & Halogen installation work

1. New tube lights installed in b2 block.
2. New switches and sockets installed in B2 block.
3. Blower work done for all meter panels on regular basis.
4. Multiple times blower work getting done for all blocks meter.
5. Bulbs and holders getting installed in different blocks and common area.

Housekeeping Related work

1. Machine cleaning of all blocks three to four times in the month.
2. Staircase scrubbing and cleaning using machine three to four times in the month.
3. Trees and plants cutting behind C Block.
4. Trees and plants cutting at the society gate.
5. Plants cutting in corridor side of the inside road.

6. Soil and dust removal from society gate and surrounded area.
7. Washing and cleaning of society gate, corner area and all surrounding area of gate on regular basis.
8. Lift cleaning of all blocks on regular basis.
9. Common area cleaning on daily basis.
10. Parking area cleaning on regular basis.
11. Cleaning of two common washrooms and maintenance both offices on regular basis using machine.
12. Washing and cleaning of both fountains on regular basis.
13. Outer area gate side and gallery side cleaning on regular basis.
14. Garbage disposal from garbage vehicle on daily basis.
15. Dustbin washing and cleaning on regular basis.
16. Railing Cleaning of all blocks on regular basis.
17. Side area cleaning beside staircases cleaning on regular basis.
18. Cobweb cleaning of parking area of all blocks.
19. Cobweb cleaning of all tower all floors on regular basis.
20. Gate side area cleaning on regular basis.
21. Guard room cleaning on daily basis.
22. Sweeping and mopping of all blocks' floors on daily basis.
23. Garbage collection from all blocks on daily basis.
24. Regular cleaning and maintenance of surrounded area of fountains and staircase of park.
25. Washing and cleaning of temple on regular basis.
26. Cleaning of partition board, society gate, society boundary wall at society main gate.
27. Kawada removal from society.
28. All blocks Kawad removal from common area and corridor area on regular basis as and when required.
29. Terrace cleaning of all blocks done.
30. Staircase railing cleaning done for all blocks more than 4 to 5 times in a month.
31. Temple cleaning inside outside done.
32. Tree and plants cutting on terrace.
33. Gamla removal from different blocks of society.

Nali Cleaning

1. Nali cleaning of D & E Block done and Malwa thrown outside society.
2. Nali cleaning of G Block done and Malwa thrown outside society.
3. Nali cleaning of F Block done and Malwa thrown outside society.
4. Nali cleaning of common area towards society gate done and Malwa thrown outside society.

Accountancy & Transparency related work

1. Sharing & Publishing Income & Expenditure Monthly report, NBH sales report, Sales report, Bank statement, Electricity bill on regular basis.
2. Doing maximum transaction through cheque and doing minimum cash recharges as and when required in case of emergencies.
3. Keeping record of all cash recharges and online recharges through QR scanner code and putting it in Income report on monthly basis.
4. Publishing all accounting related information on timely basis with as much as transparency as possible.
5. Sharing and publishing "List of work done in a particular period" on regular basis.
6. Sharing and publishing "Assets/work added to welfare of Society and Liabilities reduced of Society" on regular basis.
7. Approximately Rs. 49,50,000 works have been done with respect to "Assets / work added to welfare of Society and Liabilities reduced of Society". Society has been handed over to our team from previous RWA at a negative fund/liability of Rs. 18,00, 000 approximately.
8. All dues of electricity department have been paid off.