

List of work done from November 1, 2025 to November 30, 2025

Lift related work

1. G Block lift contractor damaged, new contractor installed.
2. F Block lift door sensor issue resolved.
3. New control panel purchased and installed in E Block lift.
4. New door drive purchased and installed in E Block lift.
5. New LOP purchased and installed in E Block lift.
6. New COP purchased and installed in E Block lift.
7. New wires purchased and complete new wiring done in E Block lift.
8. Other components and parts with cards changed and installed in E Block lift.
9. F Block lift relay card damaged and new relay card installed.
10. F Block contractor damaged and new contractor installed.
11. C Block lift door issue resolved.
12. E Block lift not working at third floor issue resolved.
13. E Block lift sixth floor door issue resolved.
14. G Block door not opening issue resolved.
15. F Block ground floor door issue resolved.

Borewell and Motor related work-

1. D and E Block motor extracted and new motor installed.
2. G Block motor wire burnt issue resolved.
3. D and E Block starter panel wire burnt resolved.
4. F block wire burnt issue resolved.

Sewer related work

1. Common area sewer at gate soil and Malwa extracted.
2. Sewer near plants in corridor cleaned and water movement resumed.
3. B2 Block sewer opened and Malwa extracted.
4. A Block sewer jam issue resolved.
5. F block side sewer jam issue resolved.

Tank Cleaning

1. Tank cleaning of G block done.
2. Tank cleaning of F Block done.
3. Tank cleaning of A Block done.
4. Tank cleaning of B1 Block done.
5. Tank cleaning of C Block done.
6. Tank cleaning of D Block done.
7. Tank cleaning of E Block done.
8. Tank cleaning of B2 Block done.

Park & Terrace cleaning & Tree Cutting work

1. Park cleaning work done.
2. Plants and trees have been cut in the park and inside the society.

3. Plants cut and removed from terrace and cleaning work done.

Electrical related work

1. New wire purchase and complete new wiring done for fountain lights and wiring.
2. New wiring done for guard room which was burnt.
3. G block motor wire burnt issue resolved.
4. Fountain lights changed wiring and repairing work done.
5. Gate light not working issue resolved.
6. A Block motor starter panel capacitor changed.
7. D block motor wire burnt issue resolved.
8. Light issue resolved for gate.
9. Motor wire burnt issue resolved multiple times for different blocks' motors.
10. Starter panel issue resolved for different block motors.
11. Wire burnt issue in different blocks common area light issue resolved.

Blower for electrical panel & Bulb, Holders & Halogen installation work

1. Blower work done for all meter panels on regular basis.
2. Multiple times blower work getting done for all blocks meter.
3. Bulbs and holders getting installed in different blocks and common area.
4. Halogens installed as and where required.

Fountain related work

1. Fountain light not working issue resolved.
2. Fountain wiring and repairing work done.

Tile installation work

1. Tile installation work done in F2 Block.
2. Tile installation work done in G Block.

Water leakage and plumbing related work

1. G Block pipe blockage issue resolved.
2. A Block shaft broken pipe leakage issue resolved and plumbing work done.
3. Soil jam issue in A Block pipe line from first floor to sixth floor soil extracted , pipe cutting and new pipe installation and plumbing work done.
4. D Block terrace water leakage issue resolved .
5. New pipes installed on D Block terrace to stop water leakage.
6. E Block terrace pipe blockage issue resolved.
7. E Block terrace broken pipe changed.
8. E block terrace new pipes installed for flow of motor supply water.
9. A Block new pipe fitting done for blocked pipe.
10. F Block two tank leakage issue resolved by m seal and sulotion.
11. A Block tank leakage issue resolved.
12. A Block pipe blockage issue resolved.

13. G block pipe blockage issue resolved.
14. Motor related plumbing issues of different blocks resolved.
15. Regular fulfillment of water supply in different blocks.

Housekeeping Related work

1. Gamla removal from different blocks of society.
2. Machine cleaning of all blocks three to four times in the month.
3. Staircase scrubbing and cleaning using machine three to four times in the month.
4. Trees and plants cutting behind C Block.
5. Trees and plants cutting at the society gate.
6. Plants cutting in corridor side of the inside road.
7. Soil and dust removal from society gate and surrounded area.
8. Washing and cleaning of society gate, corner area and all surrounding area of gate on regular basis.
9. Lift cleaning of all blocks on regular basis.
10. Common area cleaning on daily basis.
11. Parking area cleaning on regular basis.
12. Cleaning of two common washrooms and maintenance both offices on regular basis using machine.
13. Washing and cleaning of both fountains on regular basis.
14. Outer area gate side and gallery side cleaning on regular basis.
15. Garbage disposal from garbage vehicle on daily basis.
16. Dustbin washing and cleaning on regular basis.
17. Railing Cleaning of all blocks on regular basis.
18. Side area cleaning beside staircases cleaning on regular basis.
19. Cobweb cleaning of parking area of all blocks.
20. Cobweb cleaning of all tower all floors on regular basis.
21. Gate side area cleaning on regular basis.
22. Guard room cleaning on daily basis.
23. Sweeping and mopping of all blocks' floors on daily basis.
24. Garbage collection from all blocks on daily basis.
25. Regular cleaning and maintenance of surrounded area of fountains and staircase of park.

26. Washing and cleaning of temple on regular basis.
27. Cleaning of partition board, society gate, society boundary wall at society main gate.
28. Kawada removal from society.
29. All blocks Kawad removal from common area and corridor area on regular basis as and when required.
30. Terrace cleaning of all blocks done.
31. Staircase railing cleaning done for all blocks more than 4 to 5 times in a month.
32. Temple cleaning inside outside done.
33. Tree and plants cutting on terrace.

Nali Cleaning

1. Nali cleaning of D & E Block done and Malwa thrown outside society.
2. Nali cleaning of G Block done and Malwa thrown outside society.
3. Nali cleaning of F Block done and Malwa thrown outside society.
4. Nali cleaning of common area towards society gate done and Malwa thrown outside society.

Accountancy & Transparency related work

1. Sharing & Publishing Income & Expenditure Monthly report, NBH sales report, Sales report, Bank statement, Electricity bill on regular basis.
2. Doing maximum transaction through cheque and doing minimum cash recharges as and when required in case of emergencies.
3. Keeping record of all cash recharges and online recharges through QR scanner code and putting it in Income report on monthly basis.
4. Publishing all accounting related information on timely basis with as much as transparency as possible.
5. Sharing and publishing "List of work done in a particular period" on regular basis.
6. Sharing and publishing "Assets added to welfare of Society and Liabilities reduced of Society" on regular basis.
7. Approximately Rs. 39,50,000 work has been done with respect to "Assets added to welfare of Society and Liabilities reduced of Society". Society has been handed over to our team from previous RWA at a negative fund of Rs. 18,00,000 approximately.
8. All dues of secure meter contractor have been paid off.
9. All dues of electricity department have been paid off.