

List of work done from August 1, 2025 to August 31, 2025

Lift related work

1. Servicing of all blocks of lift done.
2. F Block fifth floor door not opening issue resolved.
3. A Block lift door issue resolved.
4. A Block lift door drive changed.
5. A Block lift belt changed.
6. A Block lift new roller and seal installed.
7. Extraction of water from shaft of different blocks of lift on regular basis through out this month due to rain.
8. New belt and roller installed in B1 Block lift.
9. New door belt installed in E Block lift.
10. E Block lift motor repaired.
11. New coil installed in E Block lift.
12. New contractor installed in E Block lift.
13. New PCB and earthing phase wiring done in E Block lift.
14. F Block lift not working issue resolved.
15. G Block door sensor issue resolved.
16. A Block door closing issue resolved.
17. B1 Block lift not working issue resolved.
18. C Block lift sensor issue resolved.
19. A Block lift new cuppler and belt installed.

Borewell and Motor related work-

1. G Block phase wiring burnt issue resolved.
2. New capacitor installed in A Block starter panel.
3. A Block motor wire burnt issue resolved.
4. Extraction of old motor and new motor installed in F Block.
5. C Block motor wire burnt issue resolved.
6. E Block motor wire burnt issue resolved.
7. E Block starter panel wire burnt issue resolved.
8. G Block starter panel condenser issue resolved.
9. F Block starter panel capacitor issue resolved.
10. F Block motor wire burnt issue resolved.
11. G Block motor extracted and new motor installed.
12. F Block motor extracted and new motor installed.

Fabrication and Welding work

1. Welding work done in A Block boundary saria.
2. Welding work done on terrace of A Block for shed.
3. Welding work done on terrace of F Block for shed.
4. Welding work done in staircase of G Block.
5. D Block fourth floor welding work done.
6. Welding of lights of fountain done.

7. A Block terrace shed welding and saria work done.
8. F Block shed work and welding done.
9. A Block first floor saria welding work done.
10. A Block terrace pipe repairing and welding work done.
11. G Block staircase railing welding work done.
12. B1 block shaft covering and welding work done.
13. E block new pipe welded in staircase railing.
14. Welding work done in E Block staircase railing
15. B2 Block staircase railing new pipe fitting and welding work done.
16. Fastener attached with angles and welding work done in fountain.
17. G Block lift area covered with angle and shed work with proper welding.

Sewer related work

1. Main 7 sewers with which society sewers are connected have been cleaned and opened.
2. Water logging issues in different blocks of lifts have been resolved through sewer opening and cleaning in the park.
3. F Block sewer jam opened and water movement resumed.
4. G Block sewer jam issue resolved.
5. F Block near temple sewer jam issue resolved.
6. F Block near temple sewer jam, opened and water movement resumed.
7. D Block sewer jam issue resolved.
8. Sewer jam issue near gate resolved.
9. Malwa extracted from sewers in corridor of main gate.

Shed Covering

1. New shade covering work with GI angles done for G Block lift to stop water entering into the lift.
2. G Block lift covering work done.
3. Shed fitting work done in G Block.

Chamber Covering work-

1. Two New chamber covers installed in B1 Block parking.
2. One chamber cover installed in D Block Parking.
3. New chamber covers installed in F Block parking.
4. Chamber cover installed in E and C block motor (related to previous months).
5. Chamber cover installed in B2 Block (related to previous months).
6. Two Chamber covers installed in A Block (related to previous months)

Bricks, Concrete and cementing work-

1. Cement plaster and concrete work for F Block terrace area above lift room done.
2. Concrete filling and cement plaster work done in A and F Block common area on road near sewer which was collapsed.
3. Bricks and mortar work done for closing sewer area in F Block at two points.
4. Bricks and mortar work done for installation of water tap near temple.
5. Complete tile work done in enclosed area of sewer of F Block.

6. Complete tile work done in pillar adjacent to sewer in F Block.
7. Concrete filling and plaster work on road to fill the gap.
8. Cement plaster work done for smooth flow of water near gate.
9. Concrete, cementing and plaster work done to cover the Nali of the road with 4-inch pipe.
10. Concrete and leveling work done in G Block staircase.
11. Concrete and leveling work done in D Block staircase.
12. Installation of tiles behind temple wall.
13. D Block fourth floor concrete cementing and plaster work done.
14. A Block first floor cement plaster work done.
15. A Block upper top saria covering welding and strengthening work done.
16. F Block tile repairing work done.
17. F Block third floor brick work done.
18. Cement leveling work for making dhalan done.
19. Concrete and cement filling work done in the borewell of C Block which has been damaged by rats.

Paint related work.

1. Painting of temple inside and outside done.

Park & Terrace cleaning & Tree Cutting work

1. Park cleaning work done after sewer opening and cleaning in the park.
2. Plants and trees have been cut in the park and inside the society.
3. Plants cut and removed from terrace and cleaning work done.

CCTV related work

1. CCTV components change and repair work done for non-operational CCTVs.
2. Complete check up of all CCTVs done and parts changed as required.
3. New CCTV installed in Guard room.
4. New adopter cable installed for CCTVs.

Electrical related work

1. Installation of new Halogen in B1 Block common area.
2. F and G Block neutral phase cable burnt along with burning of five MCBs, issue resolved.
3. F Block common area MCB burnt issue resolved.
4. New MCB installed in G Block common area.
5. New MCB installed at guard room.
6. Common area wiring issue of C Block resolved.
7. Wire burnt in F Block resolved.
8. Guard room light issue resolved.
9. Gate main halogen light changed.
10. Gate main halogen light wire burnt issue resolved.
11. Fountain wire burnt issue resolved.
12. Temple both fans repaired.
13. G Block motor wire burnt issue resolved.
14. Repairing of lights on all six poles of the gate.

15. New switches, sockets and box installed in temple.
16. Main gate electricity short circuit resolved and electrification work done.
17. Installation of halogen lights on the eve of Janmashtami.
18. Installation of lights in temple on eve of Independence Day and Janmashtami.
19. Wiring issue resolved of common area lights.

Blower for electrical panel & Bulb & Halogen installation work

1. Blower work done for all meter panels on regular basis.
2. Multiple times blower work getting done for all blocks meter.
3. Bulbs and holders getting installed in different blocks and common area.
4. New halogen installed in B1 Block common area.
5. Purchase of ten new halogens.

Water leakage and plumbing related work

1. Motor related plumbing issues of different blocks resolved.
2. Regular fulfillment of water supply in different blocks.
3. Pipe leakage issue in F block fixed.
4. Fountain pipe broken, new pipe and other plumbing material installed.
5. Fountain pipe broken repaired and new pipe and other plumbing material installed.
6. F Block pipe leakage issue resolved installing new pipe, t, elbow and other material.
7. Installation of 4-inch pipe in nali of the gate road.
8. Plumbing work done for installation of new tap in temple.
9. F Block broken pipe issue resolved with installation of new pipe and elbow.
10. E Block broken pipe issue resolved with installation of new pipe and elbow.
11. New gate valve and pipe installed in fountain.

Tank Cleaning and chemicalization of C Block motor & Tank

1. All tanks of C Block cleaned.
2. Chlorine chemical and fitkari put in all tanks.
3. Chlorine and fitkari put in C block motor.

Festival celebration

1. Grand celebration of Independence Day with distribution of sweets and snacks.
2. Grand celebration of Janmashtami Pooja.
3. Grand celebration of Chhathi of Laddu Gopal Jee.
4. Purchase of two new mukuts at a cost of Rs. 21000 for Radha Rani and Banke Bihari jee.
5. Celebration of Ganesh Pooja for three days in the temple.

Housekeeping Related work

1. Machine cleaning of all blocks three to four times in the month.
2. Staircase scrubbing and cleaning using machine three to four times in the month.

3. Trees and plants cutting behind C Block.
4. Trees and plants cutting at the society gate.
5. Plants cutting in corridor side of the inside road.
6. Soil and dust removal from society gate and surrounded area.
7. Washing and cleaning of society gate, corner area and all surrounding area of gate on regular basis.
8. Lift cleaning of all blocks on regular basis.
9. Common area cleaning on daily basis.
10. Parking area cleaning on regular basis.
11. Cleaning of two common washrooms and maintenance both offices on regular basis using machine.
12. Washing and cleaning of both fountains on regular basis.
13. Outer area gate side and gallery side cleaning on regular basis.
14. Garbage disposal from garbage vehicle on daily basis.
15. Dustbin washing and cleaning on regular basis.
16. Railing Cleaning of all blocks on regular basis.
17. Side area cleaning beside staircases cleaning on regular basis.
18. Cobweb cleaning of parking area of all blocks.
19. Cobweb cleaning of all tower all floors on regular basis.
20. Gate side area cleaning on regular basis.
21. Guard room cleaning on daily basis.
22. Sweeping and mopping of all blocks' floors on daily basis.
23. Garbage collection from all blocks on daily basis.
24. Regular cleaning and maintenance of surrounded area of fountains and staircase of park.
25. Washing and cleaning of temple on regular basis.
26. Cleaning of partition board, society gate, society boundary wall at society main gate.
27. Kawada removal from society.
28. All blocks Kawad removal from common area and corridor area on regular basis as and when required.
29. Terrace cleaning of all blocks done.
30. Staircase railing cleaning done for all blocks more than 4 to 5 times in a month.

31. Temple cleaning inside outside done.

32. Tree and plants cutting on terrace.

Nali Cleaning

1. Nali cleaning of D & E Block done and Malwa thrown outside society.
2. Nali cleaning of G Block done and Malwa thrown outside society.
3. Nali cleaning of F Block done and Malwa thrown outside society.
4. Nali cleaning of common area towards society gate done and Malwa thrown outside society.

Accountancy & Transparency related work

1. Sharing & Publishing Income & Expenditure Monthly report, NBH sales report, Sales report, Bank statement, Electricity bill on regular basis.
2. Doing maximum transaction through cheque and doing minimum cash recharges as and when required in case of emergencies.
3. Keeping record of all cash recharges and online recharges through QR scanner code and putting it in Income report on monthly basis.
4. Publishing all accounting related information on timely basis with as much as transparency as possible.
5. Sharing and publishing "List of work done in a particular period" on regular basis.
6. Sharing and publishing "Assets added to welfare of Society and Liabilities reduced of Society" on regular basis.
7. Approximately Rs. 35, 00,000 work has been done with respect to "Assets added to welfare of Society and Liabilities reduced of Society". Society has been handed over to our team from previous RWA at a negative fund of Rs. 18,00, 000 approximately.